

Phoenix Receiver Firmware 1.54

Phoenix receiver firmware 1.54 (v.1.54.2) is the latest version of the Phoenix receiver software, focussed on improved compatibility and system stability. This is a free update recommended for all systems and users.

New Features and Improvements in Phoenix Firmware 1.54

- * SD Card-based upgrades for RXU-8A receivers (RCS02-C) are now supported
 - * Support for receivers with motherboard BMB01-I
 - * Support for receivers with channel module BCM05-B
 - * Receiver indicates error if a channel module does not report itself correctly to the rest of the system
 - * Improved handling of schedule synchronization for ultra-long term recordings operating with daily or weekly schedules
-

Bug Fixes in Phoenix System 1.54

- * Receivers now report an error if recording files cannot be assembled in memory before transferring to card.
- * Receiver screen should now display error if a board that was not properly programmed or properly upgraded is detected
- * Fixed issue where using Chrome or Edge browsers, OS Upgrade file was downloaded with .tar extension causing OS upgrade to not proceed
- * Fixed issue where LED lights sometimes remained solid blue after start of data acquisition
- * Fixed corner cases where a receiver calibration would end up empty after appearing to start correctly