

Upgrade Receiver Firmware



Testing before an upgrade.....	2
Upgrading the Receiver Firmware	3
After the Upgrade	4
Troubleshooting	5
Technical Support Contact	7

Testing before an upgrade

Make sure the battery that the receiver is using is **fully charged** and the cables are properly connected. Run a quick recording to note the current receiver OS version and to make sure that the receiver is working as expected before upgrade.

1. Insert an **SD Card** for recording
(>= 64GB, formatted as exFat)

2. Turn on the **receiver**


2.1. Review the OS version

3. Run a quick data recording test (2 minutes)

4. Stop the recording

5. Turn off the receiver

**This will help to keep a record of the current OS version that the receiver has prior to upgrade*



Upgrading the Receiver Firmware

1. Download "osimage" and "upgrade" files from

<http://phxgeo.ca/releases/LATEST/Receiver%20Firmware>

- There are two files. In Chrome/ Edge / IE, make sure to save the file "upgrade" without any extension

**Don't save file name with any extension (.tar)*

- Using Firefox, the file will keep its name as "upgrade"

2. Put both files on a **32GB** or **smaller SD card** (must be FAT32 formatted) <https://www.sdcard.org/downloads/formatter/>

3. Put the SD card in receiver and power on

- Wait for power button to be violet, and SD card button turn blue






4. Briefly push and release the **Power button** to start upgrading

- Both LEDs will blink violet, indicating upgrade is in progress

5. Wait until both LEDs are solid violet (~15 minutes)

6. Push and hold power button for >5 seconds to power off the receiver

- After power off unplug the battery from the receiver




GPS is not required during the upgrade

After Upgrade

1. The receiver will create an **upgrade.log** file and a **receiver_backup.serial_number** file in the upgrade SD card if necessary.

** **Do Not Delete** any of these files created by the receiver until the upgrade process is verified to be complete*

2. Remove the Upgrade card, and insert a regular recording SD card (>=64 GB).
3. Connect the battery and turn on the receiver and verify that the upgrade process was completed and review the OS version



Troubleshooting

Problem:

1. SD card not detected in receiver due to format/SD hardware issues. SD led will be blinking RED and screen will display NO SD card error message

Solution:



- Make sure the SD card is of the proper recommended type
- For more information see Troubleshooting manual

Problem:

2. When the upgrade files **osImage** and **upgrade** are not detected or doesn't have the proper format then receiver will ignore those files

Solution:

- Make sure that the files **osImage** and **upgrade** are downloaded and copied to the SD card properly with no extensions, and that the card being used for the upgrade is formatted as FAT32



Troubleshooting

Problem:

- Both LEDs blinking fast in purple color. This could indicate that the **upgrade** file is not proper or the receiver is not supported by this upgrade file

Solution:

- Turn off the receiver
- Review the upgrade.log file in the SD card (*if necessary download and copy the files to the SD card again*)

Problem:

- Power LED is blinking fast RED after receiver was powered on

Solution:

- Check the upgrade card for file with similar format receiver_backup.serial_number.
For example
 - If the receiver serial number is 10111, the file name will be receiver_backup.10111.
 - If the file is available, then perform the OS upgrade procedure again, using the same osUpgrade card
- If no files were present on the SD card contact Phoenix support.

- Both button blinking purple color
Shutdown



- Power LED blinking fast Red
Shutdown





Please check out the [FAQs](#)

<https://phoenixgeophysics.freshdesk.com/>

Or email us at: support@phoenix-geophysics.com